



<b>CUSTOMER DOCUMENTATION</b>	<b>January 25<sup>th</sup> 2011</b>	<b>FIRMWARE</b>	<b>eBox Release history</b>
-------------------------------	-------------------------------------	-----------------	---------------------------------

<b>Version</b>	<b>Date</b>	<b>Changes – Additions</b>
<b>32.20</b>	January 25 <sup>th</sup> 2011	Redefined the characteristic curve of pedal position sensor
<b>32.18</b>	September 13 <sup>th</sup> 2010	Added management of inverse polarity of the valve gas sensor
<b>32.17</b>	June 3 <sup>rd</sup> 2010	Added Management of Power Valve
<b>32.16</b>	June 8 <sup>th</sup> 2009	Fixed bug that caused a bad behavior in Configuration Wizard
<b>32.15</b>	April 28 <sup>th</sup> 2009	Improved connection procedure in CAN Net
<b>32.14</b>	March 10 <sup>th</sup> 2008	Added sending value of Battery level from eBox to M4
<b>32.13</b>	February 22 <sup>nd</sup> 2008	Fixed bug on 3 <sup>rd</sup> analogic channel of EXTREME
<b>32.12</b>	February 4 <sup>th</sup> 2008	Reversed sign of accelerometer conversion
<b>32.11</b>	December 5 <sup>th</sup> 2007	Added low battery alarm signalling to MYC4
<b>32.10</b>	June 8 <sup>th</sup> 2007	<ul style="list-style-type: none"><li>▪ Fixed bug on gear calculation</li><li>▪ Added GPS maps saving in firmup management</li><li>▪ Accelerometer: The filter now works on the correct range, suppressing the frequencies of the kart vibrations</li><li>▪ Accelerometer value defaulted to ZERO when not calibrated</li><li>▪ The acquisition for Internal/External Battery values is improved</li></ul>
<b>32.07</b>	March 14 <sup>th</sup> 2007	Improved calibration process
<b>32.05</b>	February 14 <sup>th</sup> 2007	Added management of GPS Module