



## SW4 Release history

---

Version	Date	Change/additions
<b>02.44.04</b>	Sep, 18th 2025	<ul style="list-style-type: none"><li>▪ Fixed bug causing missing ECU channels</li></ul> <b>External modules</b> No changes

## SW4 Release history

Version	Date	Change/additions
<b>02.44.02</b>	Aug, 1st 2025	<ul style="list-style-type: none"><li>▪ Fixed bug could cause ACC2 lock (ACC2 firmware version 02.42.42 needed)</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>02.42.42</b> ACC2/ACC3: fixed a bug could cause ACC2 lock</li></ul>
<b>02.44.00</b>	Jul, 17th 2025	<ul style="list-style-type: none"><li>▪ Added EPM08/EPM32 support</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.42.36</b>	May, 30th 2025	<ul style="list-style-type: none"><li>▪ Fixed bug could cause incorrect configuration of the expansions</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.42.35</b>	May, 16th 2025	<ul style="list-style-type: none"><li>▪ Fixed trigger commands (e.g. change page)</li><li>▪ Increased mathematical channels</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>02.42.32</b> ACC3: fixed bug in calibration procedure</li></ul>
<b>02.42.32</b>	Apr, 11th 2025	<ul style="list-style-type: none"><li>▪ Improved ACC3 configuration/calibration</li><li>▪ Introduced restore state for toggle and multistatus button</li><li>▪ Fixed "Integer with sign bit" management</li><li>▪ Increased max CAN output frame to 24</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>02.42.30</b> ACC3: fixed bug in calibration procedure</li></ul>
<b>02.42.17</b>	Oct, 10th 2024	<ul style="list-style-type: none"><li>▪ K6/K8/K15 Keypad support</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.42.06</b>	Jun, 17th 2024	<ul style="list-style-type: none"><li>▪ LCU1S support</li></ul> <b>External modules</b> <p>No changes</p>

## SW4 Release history

Version	Date	Change/additions
<b>02.42.01</b>	Apr, 18th 2024	<ul style="list-style-type: none"><li>▪ ACC2 and ACC2 Open support</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>02.40.73</b> ACC</li><li>▪ <b>02.40.95</b> ACC2</li><li>▪ <b>02.40.95</b> GPS09c/GPS09c Open/GPS09c Pro Open</li><li>▪ <b>02.40.85</b> GPS09</li><li>▪ <b>02.40.72</b> GPS09B</li><li>▪ <b>1.32.30</b> GS-Dash</li></ul>
<b>02.40.77</b>	Oct, 11th 2023	<ul style="list-style-type: none"><li>▪ Improved AiM CAN NET</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>25.49</b> LCU-One CAN (improved warm up handling)</li><li>▪ <b>01.32.28</b> MMOD Strada Logger (fix Net table in download data)</li><li>▪ <b>02.40.73</b> ACC (fix sample time bug caused no recorded data)</li></ul>
<b>02.40.53</b>	Feb, 7th 2023	<ul style="list-style-type: none"><li>▪ GPS09C support</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.40.40</b>	Nov, 23rd 2022	<ul style="list-style-type: none"><li>▪ Added predictive reference lap management</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.40.15</b>	Jul, 8th 2022	<ul style="list-style-type: none"><li>▪ Buttons and paddle shifters support on Sim wheels</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.40.00</b>	May, 17th 2022	<ul style="list-style-type: none"><li>▪ SmartyCam 3 Sport support</li></ul> <b>External modules</b> <p>No changes</p>
<b>02.36.86</b>	Oct, 5th 2021	<ul style="list-style-type: none"><li>▪ New configuration support. Firmware needed using Race Studio 3 3.38.03</li><li>▪ "Left2", "Left3", "Right2" and "Right3" buttons used to navigate the menu</li></ul>