

Solo 2 DL Release history

Version	Date	Change/additions
02.44.04	Sep, 18th 2025	<ul style="list-style-type: none">▪ Fixed bug causing missing ECU channels External modules No changes
02.44.02	Aug, 1st 2025	<ul style="list-style-type: none">▪ Fixed bug could cause ACC2 lock (ACC2 firmware version 02.42.42 needed) External modules <ul style="list-style-type: none">▪ 02.42.42 ACC2/ACC3: fixed a bug could cause ACC2 lock
02.44.00	Jul, 17th 2025	<ul style="list-style-type: none">▪ Fixed bug could cause incorrect configuration of the expansions External modules No changes
02.42.36	May, 30th 2025	<ul style="list-style-type: none">▪ Fixed bug could cause incorrect configuration of the expansions External modules No changes
02.42.35	May, 16th 2025	<ul style="list-style-type: none">▪ Fixed trigger commands (e.g. change page) External modules <ul style="list-style-type: none">▪ 02.42.32 ACC3: fixed bug in calibration procedure
02.42.32	Apr, 11th 2025	<ul style="list-style-type: none">▪ Improved ACC3 configuration/calibration▪ Fixed "Integer with sign bit" management External modules <ul style="list-style-type: none">▪ 02.42.30 ACC3: fixed bug in calibration procedure
02.42.28	Mar, 20th 2025	<ul style="list-style-type: none">▪ ACC3 support External modules <ul style="list-style-type: none">▪ 02.42.27 ACC2▪ 02.42.27 ACC3

Solo 2 DL Release history

Version	Date	Change/additions
02.42.06	Jun, 17th 2024	<ul style="list-style-type: none">▪ LCU1S support External modules No changes
02.42.01	Apr, 18th 2024	<ul style="list-style-type: none">▪ ACC2 and ACC2 Open support External modules <ul style="list-style-type: none">▪ 02.40.73 ACC▪ 02.40.95 ACC2▪ 02.40.95 GPS09c/GPS09c Open/GPS09c Pro Open▪ 02.40.85 GPS09▪ 02.40.72 GPS09B▪ 1.32.30 GS-Dash
02.40.90	Feb, 29th 2024	<ul style="list-style-type: none">▪ Fix device lock in track creation procedure on device▪ Fix Wi-Fi not power up in some cases (Wi-Fi OFF) External modules No changes
02.40.85	Dec, 13th 2023	<ul style="list-style-type: none">▪ Add external GPS support External modules <ul style="list-style-type: none">▪ 02.40.85 GPS09
02.40.80	Nov, 28th 2023	<ul style="list-style-type: none">▪ Improved CAN network External modules No changes
02.40.77	Oct, 12th 2023	<ul style="list-style-type: none">▪ Improved AiM CAN NET External modules <ul style="list-style-type: none">▪ 25.49 LCU-One CAN (improved warm up handling)▪ 01.32.28 MMOD Strada Logger (fix Net table in download data)▪ 02.40.73 ACC (fix sample time bug caused no recorded data)



Solo 2 DL Release history

Version	Date	Change/additions
02.40.65	Jul, 4th 2023	<ul style="list-style-type: none">▪ Added ACC support External modules No changes
02.40.53	Feb, 16th 2023	<ul style="list-style-type: none">▪ Fixed Italian language handling External modules No changes
02.40.40	Nov, 23rd 2022	<ul style="list-style-type: none">▪ Added predictive reference lap management External modules No changes
02.40.21	Jul, 27th 2022	<ul style="list-style-type: none">▪ Fixed IMU platform sensors orientation External modules No changes
02.40.11	Jun, 22nd 2022	<ul style="list-style-type: none">▪ Improved GPS signal handling External modules No changes
02.36.81	Sep, 22nd 2021	<ul style="list-style-type: none">▪ Fixed accelerometers, gyros and magnetometers channels not working in some devices External modules No changes
02.36.76	Sep, 10th 2021	<ul style="list-style-type: none">▪ Production needs▪ Added RPM max value in data recall best laps page▪ Fixed accelerometers, gyros and magnetometers channels acquisition External modules No changes

Solo 2 DL Release history

Version	Date	Change/additions
02.36.34	Jun, 11th 2021	<ul style="list-style-type: none">▪ Improved GPS switch on procedure to prevent the "GPS ERROR" issue External modules No changes
02.36.18	Apr, 2nd 2021	<ul style="list-style-type: none">▪ Improved GPS initialization▪ Added 2 and 5 minutes to Auto-Off setup time in menu▪ Fixed bug that could cause half RPM value External modules No changes
02.34.29	Nov, 25th 2020	<ul style="list-style-type: none">▪ Production requirements External modules No changes
02.32.86	Aug, 21st 2020	<ul style="list-style-type: none">▪ Signalling of expansions/Wi-Fi: the two upper left shiftlights blink blue▪ Fix missing data recall graph External modules No changes
02.32.78	Jul, 10th 2020	<ul style="list-style-type: none">▪ Fixed RPM issue due to wrong RPM factor handling External modules No changes
02.32.74	Jun, 15th 2020	<ul style="list-style-type: none">▪ Fixed powerup bug that could cause the system to reset (indicated by red LED blinking slowly) External modules No changes
02.32.72	Jun, 9th 2020	<ul style="list-style-type: none">▪ Japanese language update▪ Improved timing of RS232/K-line communication (it helps with some ECU protocols)▪ Added Hour/Date info from GPS tracks▪ Added reference speed used to calculate odometers External modules No changes

Solo 2 DL Release history

Version	Date	Change/additions
02.32.57	Mar, 17th 2020	<ul style="list-style-type: none">▪ Minor stability improvements External modules No changes
02.32.52	Mar, 9th 2020	NOTE: production-only release <ul style="list-style-type: none">▪ Improved handling of poweroff after fast charge External modules No changes
02.32.49	Feb, 13th 2020	NOTE: production-only release <ul style="list-style-type: none">▪ Improved battery handling▪ Solved missing timeout on ECU channels for some serial protocol (RS232 and K-Line) External modules No changes
02.30.10	Jun, 12th 2019	<ul style="list-style-type: none">▪ Fixed bug locking the device in data recall▪ AIM CAN network improvements External modules No changes
02.30.04	May, 2nd 2019	<ul style="list-style-type: none">▪ Fixed bug on track auto-learning enabling External modules No changes
02.30.02	Apr, 19th 2019	<ul style="list-style-type: none">▪ Improved K-line protocols management▪ Added open tracks management▪ Added manual track creation on device▪ In data recall added min speed in best lap page and in all laps page External modules No changes

Solo 2 DL Release history

Page 6

Version	Date	Change/additions
02.26.55	Mar, 14th 2019	<ul style="list-style-type: none">▪ Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones) <p>External modules</p> <p>No changes</p>
02.26.50	Jan, 18th 2019	<ul style="list-style-type: none">▪ Performance Race Mode: fix wrong units of measurement in data recall page (MPH and ft were shown but values were in km/h and m)▪ ECU: support Adaptronics and Motec M4 ECU drivers <p>External modules</p> <p>No changes</p>
02.26.38	Dec, 14th 2018	<ul style="list-style-type: none">▪ Fixed calculated Performance Time▪ Fixed "+/- Best Time" display visualization▪ Added "laptime resume visualization" crossing the finish (it can be disabled by menu option) <p>External modules</p> <p>No changes</p>
02.26.12	Oct, 30th 2018	<ul style="list-style-type: none">▪ Support for Can Optical Lap(IRM_42)▪ CAN network fixes▪ 100Hz CAN output management <p>External modules</p> <p>No changes</p>
02.26.06	Oct, 5th 2018	<ul style="list-style-type: none">▪ Fixed bug on backlight set in OFF mode▪ Fixed power off for external modules when Solo 2 DL is in charging mode▪ Fixed bug on Digital output priority handling <p>External module</p> <ul style="list-style-type: none">▪ 25.47 Lambda
02.24.05	Sep, 21st 2018	<ul style="list-style-type: none">▪ Custom pages with pressure channels: unit of measure is selectable for each individual channel▪ Performance race: fixed missing performance entry in data recall▪ Fixed bug in led bar handling with predictive lap time <p>External modules</p> <p>No changes</p>

Solo 2 DL Release history

Page 7

Version	Date	Change/additions
02.22.81	Jul, 26th 2018	<ul style="list-style-type: none">▪ Fixed power consumption in low power mode (board REV00)▪ Fixed multiplexed CAN protocols management External modules No changes
02.22.67	Jun, 29th 2018	<ul style="list-style-type: none">▪ Added automatic start data recall at the end of the new test recorded▪ Fixed bug in Predictive time calculation that in some cases, with high speed applications, caused bad behavior▪ Fixed bug in System Info menu in "Hw revision" text display External modules No changes
02.22.65	Jun, 22nd 2018	<ul style="list-style-type: none">▪ Improved suspend/powerup handling▪ Support for board revisions C and E External modules No changes
02.22.58	May, 31st 2018	<ul style="list-style-type: none">▪ Support of k-line protocols External modules No changes
02.22.52	May, 18th 2018	<ul style="list-style-type: none">▪ Added "All Laps" data recall page and "Speed graph with track" data recall page▪ Added in "Wi-Fi" menu the possibility to choose the Wi-Fi channel to use instead of a random selection at boot▪ Fixed issue that, sometimes, after a shut down of the system, didn't allow to switch on again the Solo 2 DL External modules <ul style="list-style-type: none">▪ 25.47 Lambda